

## **Rear Pivot Assembly**

NOTE: TDX SP2 Rear Pivot Assembly is currently
Non-Serviceable in the field. Power wheelchair must be returned to
Invacare Corporation for repair.





**Rear Pivot Assembly** 

Item				Quantity Per	
Number	Note	Part Number	Description	Package	Assembly
2	Α	40117X006	Bearing (5/8")	1	2
3	Α	1110717	Ring, Tolerance	1	2
NOTE: A - Item 2 and 3 are the only serviceable parts available at this time.					