Rear Pivot Assembly

NOTE: TDX SP2 Rear Pivot Assembly is currently
Non-Serviceable in the field. Power wheelchair must be returned to
Invacare Corporation for repair.



