

Rear Pivot Assembly Mounting Hardware

NOTE: TDX SP2 Rear Pivot Assembly Mounting Hardware is currently Non-Serviceable in the field. Power wheelchair must be returned to Invacare Corporation for repair.

