READ THIS FIRST

Service parts are no longer available

for the following Lift Out Chair Models:

LC2300 LC2700 LC2900 LC3100 LC3300 LC4100 LC4300 LC4300W LC4500

SPC_050A