


Controller, Harness, Cables, Programmer and Hardware

MKIV Quad Pulse

Effective 12/19/03, MK5 NX-80 replaced MKIV RII as standard electronics on 400 Lb. limit chairs and PTO seating system chairs.

Effective 4/1/04, MK5 NX-80 replaced MKIV RII as standard electronics on 300 Lb. limit chairs.



Controller, Harness, Cables, Programmer and Hardware

MKIV Quad Pulse

Effective 12/19/03, MK5 NX-80 replaced MKIV RII as standard electronics on 400 Lb. limit chairs and PTO seating system chairs.

Effective 4/1/04, MK5 NX-80 replaced MKIV RII as standard electronics on 300 Lb. limit chairs.

Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1		1116608-NLA	NLA - Shroud, MKIV Controller	1	1
2		1114308	Screw, Phillips Pan Head Tap (#10-32 x 1/2")	1	2
3		1042484-NLA	NLA - Screw, Hex Head (5/16-18 x 2")	1	2
4		1117042	Controller, MKIV Quad Pulse	1	1
5		1026158	Locknut (5/16-18)	1	1
6		1116430-NLA	NLA - Bracket, Port, Black	1	1
7		1037373-NLA	NLA - Cover, Splash	1	1
8		1040226-NLA	NLA - Rivet, Nylon	1	1
9		1074983-NLA	NLA - Cable, Limit Switch Sensor	1	1
10		1094872	Cable Option with Phono Jack	1	1
11		1092912-NLA	NLA - Programmer Extension Cable Assembly (18" Long)	1	1
12	E	1116613-NLA	NLA - Cable, Joystick Jumper	1	1
13		1116609-NLA	NLA - Harness, Wire, MKIV Quad Pulse, M91	1	1
14		1101099-NLA	NLA - Fuse, Buss ATC-20 (20 AMP)	1	1
15		1090117-NLA	NLA - Fuse - Buss Mini ATM-15 (15 AMP)	1	1
16	A,H	1112783-NLA	NLA - Bracket with Hardware, Controller, M91/M94	1	1
17			NLA - Screw (#8-32 x 1/2")	1	1
18			NLA - Screw, Hex Head (5/16-18 x 3/4")	1	1
19			Washer, Steel (5/16 x 3/4 x 1/16")	1	1
20			Locknut (5/16-18)	1	1
21			NLA - Bracket, Controller Mounting, Black	1	1
			Tie Wrap (11-1/2" L)	1	1
22	F	1020818	Switch, Red Flex Ribbon (Tape) Reset	1	1
22	G	1123276	Kit, Switch, Black Egg Reset w/ Hook/Loop Adhesive Back Fastener & Attaching Screws (EGSBLK)	1	1
23		1109091-NLA	NLA - Programmer, Remote	1	1
	B,C	1064404-NLA	NLA - Virtual Service Modem Kit	1	1
	B,D	1091631-NLA	NLA - Virtual Service Software Kit	1	1
	B,C	1103051-NLA	NLA - MKIV One 2 One Software Kit	1	1
	B	1095204-NLA	NLA - Cable, Virtual Service, Charger/Modem	1	1
	B	1091980-NLA	NLA - Disk, 3.5 H.D. Floppy with V.S. Software	1	1
	B	1091637-NLA	NLA - Adaptor, Null Modem	1	1
	B	1091636-NLA	NLA - Service Manual - V.S. Software Kit	1	1

NOTE: A - Includes items 17-21
 B - Not Shown
 C - Part number 1095204 is not available for individual sale
 D - Part numbers 1095204, 1091980, 1091637 and 1091636 are available for individual sale
 E - Joystick jumper cable is not used when a Power Tilt Only (PTO) seating system is present
 F - Before 5/24/04
 G - Not Shown. After 5/23/04 the Egg Reset Switch replaced the Red Flex Ribbon (Tape) Reset Switch
 H - Part number 1110665 item #21 is no longer available for individual sale. Order item #16 as a replacement. Tie Wrap (not shown) is used for other Controller applications.