


MKIV Controller, Programmer and Attaching Hardware



MKIV Controller, Programmer and Attaching Hardware

Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1		1105707-NLA	NLA - Controller, MKIV Quad Pulse	1	1
1	B,D	1095269-NLA	NLA - Controller, MKIV RII, Retro	1	1
2		7930323-NLA	NLA - Package, Locknut (1/4-20)	25	1
3	E	1018739	Washer (1/4 x 5/8 x 3/32")	1	2
3		1020818	Switch, Red Flex Ribbon (Tape) Reset	1	1
3	G	1123276	Kit, Switch, Black Egg Reset w/ Hook/Loop Adhesive Back Fastener & Attaching Screws (EGSBLK)	1	1
3	F	1018739	Washer (1/4 x 5/8 x 3/32")	1	6
4	A	1109091-NLA	NLA - Programmer, Remote	1	1
5	C	1064404-NLA	NLA - Virtual Service Modem Kit	1	1
	C	1095204-NLA	NLA - Cable, Virtual Service, Charger/Modem	1	1
	C	1091631-NLA	NLA - Virtual Service Software Kit	1	1
	C	1091980-NLA	NLA - Disk, 3.5 H.D. Floppy with V.S. Software	1	1
	C	1091637-NLA	NLA - Adaptor, Null Modem	1	1
	C	1091636-NLA	NLA - Service Manual - V.S. Software Kit	1	1
	C	1095204-NLA	NLA - Cable, Virtual Service, Charger/Modem	1	1
	C	1046117-NLA	NLA - Printer and Interface	1	1
	C	1026572-NLA	NLA - Paper, Printer	1	1
	C	1027280-NLA	NLA - Harness, Printer Wiring	1	1

NOTE: A - Remote programmer #1109091 with the dual connectors (3-pin and 5-pin) is the only programmer functionable with the new RII joystick #1092610.
 B - RII retro controller after 4/30/00 and new RII joystick #1092610 serve as direct replacements for Joystick/Controller #1080723.
 C - Not Shown.
 D - After 4/30/00.
 E - Non-Weight Shifting Tilt.
 F - Weight Shifting Tilt.
 G - Not Shown. After 5/23/04 the Egg Reset Switch became available as a service part and can be used as a direct replacement for the tape reset switch part # 1020818.