

# Warranty Replacement Parts

Part Number	Description	Quantity per Assembly
1121089E-NLA See Note(s) B, A	WARR RPLMT - Charger, Battery, 3 Amp (Off Board)	1
1134124E-NLA See Note(s) C	WARR RPLMT - Motor and Gearbox Assembly - Right	1
1134125E-NLA See Note(s) C	WARR RPLMT - Motor and Gearbox Assembly - Left	1
<p>NOTE: A - See Category "Electronics - MK5 NX Controllers &amp; Battery Charger (For Ser. # Before 08C &amp; After 09F)" for additional information.</p> <p>B - See Category "Electronics - Joystick/Controller - A Series Integrated (For Ser. # 08DSZ190001 - 09ESZ)" for additional information.</p> <p>C - See Category "Motors - Drive Wheel &amp; Hardware" for additional information.</p> <p>Chairs manufactured with motors before serial number 08DSZ190001 and after serial numbers beginning with 09E generate reverse error codes. During these periods, an error code on the right side motor would be an indication that the left side motor must be replaced. An error code on the left side motor would be an indication that the right side motor must be replaced.</p>		