


# MKIV Recliner Control and Recliner Cable

**NOTE: Recliner control is not adaptable with 2nd Generation Powered Seating Systems. Actuator damage may occur.**



## MKIV Recliner Control and Recliner Cable

**NOTE: Recliner control is not adaptable with 2nd Generation Powered Seating Systems. Actuator damage may occur.**

Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1		1054376-NLA	NLA - Control, Recliner	1	1
2		1095501-NLA	NLA - Fastener, Dual Lock Hook and Loop Adhesive (2" W x 12" L)	1	1
3		1098905-NLA	NLA - Cable Assembly, 24 Volt, Anderson/P.T.O.	1	1
	A	1005151-NLA	NLA - Cable, Recliner	1	1

NOTE: A - Not Shown