
Base Frame Assembly

NOTE: "Base Frame Assembly, Headtube Bearings and Internal Retaining Rings are not available as a service part."

Wheelchair must be returned to Invacare when items listed need replaced. Contact Invacare Customer Service for additional assistance.



Base Frame Assembly

NOTE: "Base Frame Assembly, Headtube Bearings and Internal Retaining Rings are not available as a service part."

Wheelchair must be returned to Invacare when items listed need replaced. Contact Invacare Customer Service for additional assistance.

	ltem				Quantity Per	
N	lumber	Note	Part Number	Description	Package	Assembly
	1		60127923	Kit, Cap, End (Pkg. of 2)	2	1
				Cap, End	1	2
				Sheet, Insert Parts Service	1	1