


MKIV Recliner Control and Recliner Cable

NOTE: Recliner control is not adaptable with 2nd Generation Powered Seating Systems. Actuator damage may occur.



Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1		1054376-NLA	NLA - Control, Recliner	1	1
2		1095501-NLA	NLA - Fastener, Dual Lock Hook and Loop Adhesive (2" W x 12" L)	1	1
3	A	1098905-NLA	NLA - Cable Assembly, 24 Volt, Anderson/P.T.O.	1	1
		1005151-NLA	NLA - Cable, Recliner	1	1

NOTE: A - Not Shown