


MKIV Controller, Programmer and Attaching Hardware



MKIV Controller, Programmer and Attaching Hardware

Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1	A	1092916-NLA	NLA - Hardware, Controller Attaching	1	1
2		60290X002	Locknut (5/16-18)	1	2
3		1013560-NLA	NLA - Screw, Hex Head (5/16-18 x 1-1/2")	1	2
4		1023263-NLA	NLA - Washer, Internal Tooth (M8)	1	4
5		1093999-NLA	NLA - Spacer, Controller Attaching, Black (3/8 x 5/8 x 1/2")	1	1
6	C	1105707-NLA	NLA - Controller, MKIV Quad Pulse	1	1
7		1020818	Switch, Red Flex Ribbon (Tape) Reset	1	1
7	G	1123276	Kit, Switch, Black Egg Reset w/ Hook/Loop Adhesive Back Fastener & Attaching Screws (EGSBLK)	1	1
8		1109091-NLA	NLA - Programmer, Remote	1	1
	B,D	1064404-NLA	NLA - Virtual Service Modem Kit	1	1
	B,E	1091631-NLA	NLA - Virtual Service Software Kit	1	1
	B,D	1103051-NLA	NLA - MKIV One 2 One Software Kit	1	1
	B,F	1046117-NLA	NLA - Printer and Interface	1	1
	B	1095204-NLA	NLA - Cable, Virtual Service, Charger/Modem	1	1
	B	1091980-NLA	NLA - Disk, 3.5 H.D. Floppy with V.S. Software	1	1
	B	1091637-NLA	NLA - Adaptor, Null Modem	1	1
	B	1091636-NLA	NLA - Service Manual - V.S. Software Kit	1	1
	B	1026572-NLA	NLA - Paper, Printer	1	1
	B	1027280-NLA	NLA - Harness, Printer Wiring	1	1
NOTE: A - Includes Items 2-5. B - Not Shown C - It is recommended that Items 2-4 be ordered when a new controller is needed for chairs built before 4/12/01. D - Part number 1095204 is available for individual sale E - Part numbers 1091980, 1091637, 1091636 and 1095204 are available for individual sale F - Part numbers 1026572 and 1027280 are available for individual sale G - Not Shown. After 5/23/04 the Egg Reset Switch became available as a service part and can be used as a direct replacement for the tape reset switch part # 1020818.					