


# Wheel Lock - Hublock Replacement Kits (Before 11/01/07 - Currently Out of Stock)

Invacare does not recommend the use of service part number 1132357 and/or 1132358 for replacement hublock cables for wheel chairs manufactured before November 1, 2007.



## Wheel Lock - Hublock Replacement Kits (Before 11/01/07 - Currently Out of Stock)

Invacare does not recommend the use of service part number 1132357 and/or 1132358 for replacement hublock cables for wheel chairs manufactured before November 1, 2007.

Item Number	Note	Part Number	Description	Quantity Per	
				Package	Assembly
1		1153654	Kit, Hublock Replacement, Hand Operated	1	1
			Actuator w/ Cable Assembly, Hand Operated	1	1
			Hublock Hand Operated Latch Assembly	1	1
			Hublock Hand Operated Latch Assembly	1	1
			Screw, Socket Button Head (#10-32 x 1")	1	2
			Box, Junction Cable	1	2
			Pin, Dowel (3/16 x 1/2")	1	1
			Locknut (#10-32)	1	2
			Bracket, Junction Cable, Black	1	1
			Tie Wrap (5-5/8" L)	1	1
			Locknut (1/4-28)	1	4
			NLA - Service Manual, Hublock	1	1