


Label Locations For TRRO and TRBKTS Options


WC/19 Warning Label is a non-serviceable part.
Call Technical Services for assistance at
(1-800-832-4707).



Occupant restraint pelvic belt
conforms with ANSI/RESNA.
WC/19 Warning Label is sewn
onto the pelvic belt assembly.

TRRO Option Label Locations

Seat/Chest Positioning Strap
DOES NOT conform with ANSI/RESNA.
WC/19 Warning Label is sewn
onto the positioning strap.



Non TRRO/TRBKTS Option Label Locations