




Label Locations For TRBKTS Option



Front View of Wheelchair



Rear View of Wheelchair



Seat/Chest Positioning Strap DOES NOT conform with ANSI/RESNA WC/19 Warning Label is sewn onto the positioning strap

TRBKTS Option Label Locations